

M E M O R A N D U M

DATE: November 1, 1988

TO: LPC - Division File

FROM: W. G. Schaufelberger *WGS*

SUBJECT: 1630450038 - St. Clair County - East St. Louis/Wastex
ILD980700744
Compliance

EPA Region 5 Records Ctr.



315968

On October 25, 1988, Pat McCarthy, Mike Grant and this writer conducted an inspection at Wastex to determine compliance with the continuance granted on the Court Order to Show Cause dated September 19, 1988. Conditions of the continuance and actions Wastex is taking are as follows:

1. Cease acceptance of any further wastes. Per Terry Hein, Wastex has not received any waste since August 3, 1988, nor shipped any out since that date.
2. Overpack any leaking or likely to start leaking drums. Per Terry Hein 60 drums noted in the above condition during the September 14, 1988 ISS inspection were either corrected or overpacked. However, records tracking this action are in an internal memo that was not readily available during the inspection. Mr. Hein agreed to send a copy of this memo to the Collinsville regional office. Upon receipt of this memo, an inspection will be conducted on the condition of the drums.
3. Properly close any drums which are not closed and close any bungs. This condition and remedial actions taken are explained in the above, Condition #2.
4. Remove and properly store the material currently in tank #8. Per Terry Hein, 300 gallons of material were pumped from tank #8 and placed in tank #9 on September 29, 1988. The hole was fixed by using refractory brick and Quik-Set cement. A new valve was also added and the tank has been taken out of service. However, during this inspection tank #8 was observed leaking. The material left in the tank was seeping out onto the ground.

WGS:jlr/32

cc: Bruce Carlson
cc: DLPC - Collinsville

RECEIVED

NOV 7 1988

EPA-DLPC

Date: APRIL 28, 1982

Time: 3:40 A.M. P.M.

Photograph By:

Al M. Spencer

Location: LPC- 16304531

ST. CLAIR Co.

E. ST. CLAIR / WASTEX #2

Comments: Photograph taken

toward the NORTH

Date: APRIL 28, 1982

Time: 3:40 A.M. P.M.

Photograph By:

Al M. Spencer


Location: LPC- 16304531

ST. CLAIR Co.

E. ST. LOUIS / WASTEX #2

Comments: Photograph taken

toward the NORTH



RECEIVED

JUN 7 1982

E.P.A. — U.S. DEPT. OF HEALTH
STATE OF ILLINOIS

DATE: October 26, 1988

TIME: 2:00 p.m.

I.D. 1630450038 FOS

St. Clair County

E.St.Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

West

ROLL# 949 PHOTO# 5

PHOTOGRAPH BY:

Andy Schaffner



DATE: _____

TIME: _____

I.D. _____

County _____

PHOTOGRAPH TAKEN TOWARD THE:

ROLL# _____ PHOTO# _____

PHOTOGRAPH BY:

RECEIVED

NOV 7 1988

IEPA-DLPC

DATE: March 24, 1989

TIME: 10:47 a.m.

I.D. 1630450038 FOS

St. Clair County

E.St.Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

North

ROLL# 1042 PHOTO# 6

PHOTOGRAPH BY:

William D. [Signature]



DATE: March 24, 1989

TIME: 10:47 a.m.

I.D. 1630450038 FOS

St. Clair County

E.St.Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

South

ROLL# 1042 PHOTO# 7

PHOTOGRAPH BY:

William D. [Signature]



DATE: March 24, 1989

TIME: 10:47 a.m.

I.D. 1630450038 FOS

St. Clair County

E.St.Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

North

ROLL# 1042 PHOTO# 6

PHOTOGRAPH BY:

William D. [Signature]



DATE: March 24, 1989

TIME: 10:47 a.m.

I.D. 1630450038 FOS

St. Clair County

E.St.Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

South

ROLL# 1042 PHOTO# 7

PHOTOGRAPH BY:

William D. [Signature]



DATE: November 6, 1987

TIME: 11:26 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:

Northeast

ROLL# 756

PHOTO# 11

PHOTOGRAPH BY:

Mark McCarthy



DATE: November 6, 1987

TIME: 11:33 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


Northeast

ROLL# 756

PHOTO# 14

PHOTOGRAPH BY:

Mark McCarthy



RECEIVED
NOV 30 1987
IEPA/DLPC

DATE: November 6, 1987

TIME: 11:28 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


Southeast

ROLL# 756

PHOTO# 12

PHOTOGRAPH BY:

McCarthy



DATE: November 6, 1987

TIME: 11:29 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


Northeast

ROLL# 756

PHOTO# 13

PHOTOGRAPH BY:

McCarthy



DATE: November 6, 1987

TIME: 11:04 a.m.

I.D. 1630450038

St. Clair County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:

South Southwest

ROLL# 756 PHOTO# 2

PHOTOGRAPH BY:

McCarthy



DATE: November 6, 1987

TIME: 11:04 a.m.

I.D. 1630450038

St. Clair County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:

South

ROLL# 756 PHOTO# 3

PHOTOGRAPH BY:

McCarthy



DATE: November 6, 1987

TIME: 11:06 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:

Southwest

ROLL# 756

PHOTO# 4

PHOTOGRAPH BY:

MMcCarthy



DATE: November 6, 1987

TIME: 11:10 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


Northwest

ROLL# 756

PHOTO# 5

PHOTOGRAPH BY:

MMcCarthy



DATE: November 6, 1987

TIME: 11:18 a.m.

D. 1630450038

St. Clair County

E. St. Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

Northwest

DLL# 756 PHOTO# 7

PHOTOGRAPH BY:

McCathy



DATE: November 6, 1987

TIME: 11:18 a.m.

D. 1630450038

St. Clair County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:

Southeast

DLL# 756 PHOTO# 8

PHOTOGRAPH BY:

McCathy



RECEIVED
NOV 30 1987
IEPA/DI PC

DATE: November 6, 1987

TIME: 11:21 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


South

ROLL# 756

PHOTO# 9

PHOTOGRAPH BY:

Mark McCarthy



DATE: November 6, 1987

TIME: 11:21 a.m.

I.D. 1630450038

St. Clair

County

E. St. Louis/Wastex

PHOTOGRAPH TAKEN TOWARD THE:


Northeast

ROLL# 756

PHOTO# 10

PHOTOGRAPH BY:

Mark McCarthy



DATE: November 6, 1987

TIME: 11:00 a.m.

I.D. 1630450038

St. Clair County

E. St. Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

Southeast

ROLL# 756 PHOTO# 1

PHOTOGRAPH BY:

McCarthy



DATE: November 6, 1987

TIME: 11:17 a.m.

I.D. 1630450038

St. Clair County

E. St. Louis/Wastex


PHOTOGRAPH TAKEN TOWARD THE:

North

ROLL# 756 PHOTO# 6

PHOTOGRAPH BY:

McCarthy



Date: June 20, 1984

Time: 9:33 A.M. P.M.

Photograph By:

Kenneth Mensing


Location: LPC 16304538

St. Clair Co.

E.St.Louis / Wastex #2

Comments: Photograph taken

toward the



Date: June 20, 1984

Time: 9:33 A.M. P.M.

Photograph By:

Kenneth Mensing

Location: LPC 16304538

St. Clair Co.

E.St. Louis / Wastex #2

Comments: Photograph taken

toward the



RECEIVED

JUL 17 1984

E.P.A. — D.L.P.C.
STATE OF ILLINOIS